

Buyer: Connie Heinrichs

2952 OF  
Dept of Roads

Opening Date: 06/15/09

				AWARD See Attached Explanation			
Line #	Rotary Mount Boom Mower			Murphy Tractor & Equip. Co.	RL Parson's & Son ECI	RL Parson's & Son ECI	Tiger Corporation
	Description	Qty	UOM	Unit Price	Unit Price	Unit Price	Unit Price
1	<b>Rotary Mount Boom Mower</b> - 3 point mount per specs	2	EA	\$30,703.00	\$29,594.00	\$33,451.00	\$26,764.00
	Make:			Diamond/Orsi Group	Bom Ford	Bom Ford	Tiger
	Model:			River - HD2060R	Falcon 6.0 T	Falcon 6.0 T Electric	TRB-60C
2	<b>Equipment shop repair manual</b> (additional copy)	2	EA	\$35.00		\$0.00	
3	<b>Equipment parts manual</b> (additional copy)	2	EA	Included in repair manual		\$0.00	
4	<b>Wet blade system</b> to apply herbicide to cut material	2	EA	\$4,975.00	NA	NO	\$4,436.00
Payment Terms				100% 30	Net 30	Net 30	
Delivery Days ARO				195	90	90	40-60
Comments for Murphy Tractor & Equip. Co.				Line 1 - Must be special ordered due to 1,000 PTO req. & proportional controls. Tractor will need 2 wheel weights in each of the left hand wheels. Mower is "puller type" & mows to right and rear of the power unit (not bi-directional). Line 2 - Must order w/boom mower (Factory Installed Only)			

**No Bid**  
Platte Valley

See Next Page for Award Explanation


DATE: June 16, 2009

TO: DAS Materiel, Connie Heinrichs

FROM: Fleet Management, Mike Blacksher

THRU: Janie Vrtiska, Fleet Manager

SUBJECT: 2952 OF



Apparent first lowest bidder, Tiger Corporation met all of the specifications except for the mounting.

#### **6. MOUNTING SYSTEM**

A. States: Three point and PTO mounting with Category II/III hitch. Vendor is furnishing mower to be mounted to loader pockets which are only available on bi-directional tractors. NDOR is requiring the Category II/III hitch so the mower can be moved to tractors other than the Bi-directional tractors. The intent of this bid was to have mowers that could also be used on all available tractors in the NDOR fleet after the bi-directional tractors are surplus.

Apparent second lowest bidder, RL Parson's & Sons ECI failed to meet specifications on the following items.

#### **1. MOWER**

Vendor checked NO on C., G., and K. with no comments.

#### **2. HYDRAULIC SYSTEM**

Vendor checked NO on C., F., and H. C. States: Hydraulic drive system shall produce not less than 3,200 PSI. Vendor is furnishing 3,000 PSI.

#### **3. CONTROLS**

B. Vendor checked NO. We requested hydraulic controls, vendor is furnishing low friction cable controls.

#### **4. BOOM**

Vendor checked NO on A. and I.

#### **5. OTHER FEATURES**

Vendor checked NO on A. and B.

#### **6. MOUNTING SYSTEM**

Vendor checked NO on D.

#### **7. MANUALS**

Vendor checked NO on B.

#### **8. MISCELLANEOUS**

Vendor checked NO on D.

Vendors secondary bid was higher than the next lowest bidder and also had numerous NO's checked on this bid also.

Recommend awarding bid to third lowest bidder, Murphy Tractor & Equipment Co, 6100 Arbor Road, Lincoln, NE 68517-3211 with their bid of \$30,703.00 each. We would just like to purchase Line # 1 on each mower and pass on lines 2, 3, and 4. The mower bid meets specifications and intent of the bid.