

				AWARD							
Line #	Compact rubber Track Skid Loader			Hamilton Equipment Co	Murphy Tractor & Equipment Co	Nebraska Equipment Inc	NMC, Inc.	Scott Van Keppel	Stutheit Implement Co.	Stutheit Implement Co. Alternate Bid:	Titan Machinery
	Description	QTY	UOM	Unit Price	Unit Price	Unit Price	Unit Price	Unit Price	Unit Price	Unit Price	Unit Price
1	Compact Rubber Track Skid Loader	1	EA	\$ 47,600.00	\$ 57,698.00	\$ 55,750.00	\$ 60,345.00	\$ 49,100.00	\$ 50,250.00	\$ 54,060.00	\$ 58,191.00
	Make:			Bobcat T-770	John Deere	Kubota	CAT	Volvo	John Deere	John Deere	CASE
	Model:			T-770	333D	SVL90	299C	MCT135C	329D	333D	TV380
	Engine:			Kubota Diesel	5030 HT	Kubota	C3.4T	JCB Dieselmax	Power Tech E 5030HT	Power Tech E 5030HT	CASE 432T/M3
OPTIONS											
2	Equipment Shop Repair Manual	1	EA	\$ 110.00	\$ 200.00	\$ 130.00	\$ 450.00	\$ 250.00	\$ 150.00	\$ 150.00	\$ 447.00
3	Engine Shop Repair Manual	1	EA	included in #2	\$ 200.00	same as above	Included in serviceman	included	\$ 150.00	\$ 150.00	
4	Equipment Parts Manual	1	EA	\$ 95.00	\$ 200.00	\$ 35.00	Standard	included	\$ 145.00	\$ 145.00	on-line
5	Engine Parts Manual	1	EA	included in #4	\$200.00	same as above	Standard	included	\$ 145.00	\$ 145.00	on-line
6	Two Speed Transmission	1	EA	\$1,250.00	\$2,100.00	Standard	Standard	\$1,500.00	\$2,000.00	standard equipment	inc.in base machine price
7	Speed Hydraulic Drive and Reversing Option	1	EA	Not Required	\$650.00	NA	\$3,500.00	NA	\$ 650.00	\$650.00	N/A
8	Air Ride Suspension Seat	1	EA	\$300.00	\$375.00	\$500.00	Standard	\$600.00	\$350.00	\$350.00	\$396.00
9	Additional Delivery Charges Outside the Lincoln/Raymond Area	1	MI	\$2.00/mile Round Trip	\$4.00/mile	\$3.00	\$2.00/mile	\$3.50/mi	\$0.00	\$0.00	\$4.50
Payment Terms				Net% 30 DAYS	100% 30 DAYS	100% 30 DAYS	Net% 30 DAYS			0% 30 DAYS	Net% 30 DAYS
Delivery Days ARO				90* or sooner if possible	90	180	60	120		90	90-120
Comments				Truck Roller Suspension System: \$1,500.00							

**Award Explanation**

Titan Machinery life cycle cost is lower at a cost of \$12.75, but they do not meet specifications on items 2B, 2C, 2F & 3B.