

| Line # | | | SECONDARY AWARD E85 ONLY | | PRIMARY AWARD |
|--------|---|--|-----------------------------|---------------------------------|---------------------------------|
| | Compact Extended Cab 4-Door 4x4 Pickup | Anderson Ford | Performance Dodge | Sid Dillon GMC | Sid Dillon Wahoo Inc |
| 1 | Base Price | \$19,840.00 | \$19,130.00 | \$18,997.00 | \$18,757.00 |
| | Make: | 4.0 V-6 | Dodge | GMC | Chevrolet |
| | Model: | Ranger SC | Dakota Extended Cab | Canyon | Colorado |
| | GVWR: | 5280 | 6010 | 5300 | 5300 |
| | Series, Code, Trim Level: | XLT | Bighorn' ND5M33 | Canyon CT15653-WT | Colorado-CT15653-WT |
| | Engine | 4.0 V-6 | 3.7L V-6 | 3.7L DOHC SFJ | 3.7L 5 cyl SFI |
| | EPA | 16-21 Hiway | 14-18 | 16 city/22 hwy | 16 city/22 hwy |
| 2 | E85 model price | N/A | \$20,063.00 | N/A | N/A |
| | Engine | | 4.7L V-8 FFV | N/A | N/A |
| | Alternate Engine Sizes: | | | | |
| 3 | Engine (other gas). | N/A | \$933.00 | (\$497.00)/LLV | (\$497.00) LLV |
| | Specify Engine Size: | | 4.7L V-8 FFV | 2.9L DOHC 4 cyl | 2.9L DOHC 4 cyl |
| 4 | 40-20-40 or 60-40 style seat w/ lumbar (vinyl) support | N/A | N/A | \$97.00 | \$97.00 |
| 5 | Bucket type seats - Vinyl covering | N/A | N/A | N/A | N/A |
| 6 | Bucket type seats - Cloth w/vinyl trim | \$450.00 | STD | \$1,097.00 Required 1 LT Pkg | \$1,097.00 Required 1 LT Pkg |
| | 7 | Deduct for no sliding rear-vision window (deduct) | (\$90.00) | (\$123.00) | (\$97.00) |
| 8 | Second Power Outlet | \$250.00 | STD | STD | STD |
| 9 | Trailer towing package (deduct) | STD | (\$167.00) | (\$147.00) | (\$147.00) |
| 10 | Cargo light | STD | STD | \$97.00 | \$97.00 |
| 11 | Electronic compass/temp display | N/A | N/A | \$497.00 Dealer Installed | \$497.00 Dealer Installed |
| | 12 | Standard Paint - Attach List and Identify as No Additional Cost Paints | NC | See attached sheet | NC |
| 13 | For Department of Roads Use: Yellow color of: Dodge #PY5269, Ford #84S53, Chevrolet/GMC #WA-253A code (9W3) | NC | See attached sheet | NC-9W3 | NC-9W3 |
| 14 | Extra Cost Paint- Attach List and Identify as Extra Cost Paints | NC | See attached sheet | \$597.00 | \$597.00 |
| 15 | Snow plow attachment of pickup manufacturer's (Western, Boss, Meyer, and Northman brands with power angling, 8-foot bolt on blade, plow head and turn lights, snow deflector, blade markers.) | NC | No Bid | \$4,097.00 N/A on Model Bid | \$4,097.00 N/A on Model Bid |
| | Specify equipment included: | | | 7' 0" Boss TB9567 | 7' 0" Boss TB9567 |
| 16 | Additional remote fob from manufacturer | \$90.00 | Inc. in Bid | \$97.00 | \$97.00 |
| 17 | Equipment & engine service repair manual. | \$400.00 | \$493.75 | \$297.00 | \$297.00 |
| 18 | Equipment & engine service repair manual on CD ROM | \$750.00 | \$112.50 | \$797.00 when available | \$797.00 when available |
| 19 | Equipment & engine parts manual | \$400.00 | N/A | N/A | N/A |

| | | | | | |
|----------------------|--|---|---|--------------|--------------|
| 20 | Equipment & engine parts on CD ROM | N/A | \$375.00 | N/A | N/A |
| 21 | Additional costs of charges for vehicle drop shipment outside the Lincoln area. Drop shipment charges would be for vehicles bought by political entities and other Divisions of Government. | \$490.00 | \$400.00 | \$400.00 | \$400.00 |
| 22 | Two wheel drive (deduct) | (\$1,200.00) | (\$3,728.00) | (\$1,297.00) | (\$1,297.00) |
| LAW ENFORCEMENT ONLY | | | | | |
| 23 | Factory disconnect of daylight running lights | \$25.00 | No Bid | \$147.00 | \$147.00 |
| 24 | Factory disconnect of factory dome light or courtesy lamps | \$150.00 | No Bid | \$97.00 | \$97.00 |
| 25 | Courtesy/courtesy lamp: To be centered not more than approximately 4" to 8" From the top of the windshield to light the driver's area and controlled by rotating headlamp switch to maximum position or by a separate switch. This may require adding an additional light. Dealer installation is acceptable if not available from the factory. | \$250.00 | No Bid | \$197.00 | \$197.00 |
| 26 | Spotlight: Mounted on driver's side (left door post). Spotlight shall be fused in accordance with manufacturers specifications. Unity # 250 (or equal) 5-inch diameter spotlight with halogen lamp is preferred. Unity #225 (or equal) 6-inch diameter spotlight with halogen lamp is an acceptable substitute. All spotlights for one make and model of vehicle must be the same size. Dealer installation is acceptable if not available from the factory. | \$550.00 | No Bid | \$397.00 | \$397.00 |
| Payment Terms | | 100-30 | | 0-15 | 0-15 |
| Delivery Days ARO | | 90-120 | 90-120 | 45-120 | 45-120 |
| Comments | | 1.A: yellow available in Extended Cab XL Model and Regular Cab XL Model. 1.K: Carpet only on XLT Model. 4.B: Battery 540 CCA Warranty 3/36 Bumper to Bumper, 5/60 Powertrain, 5/100K on Corrosion | 1.F: body side molding-N/A 1.K: Carpet 1.O: Chrysler-Inc. in Bid. 4.B: Battery-750 AMP w/Tow Group Cloth 40/20/40 split Bench Seat included with bid. Extra Cost Paint Deep Water Blue Pearl Coat and Inferno Red Crystal Pearl Coat (13) Yellow paint requires a minimum of 50 units. | | |