

Line #	Digital Video Surveillance Recorders			Aprisa Technology LLC.		Business Services		Clark Security Products		Compulan Center Inc.	
	Description	Qty	UOM	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price
1	8 channel video surveillance Digital Video Recorder system unit	4	ea	\$3,740.88	\$14,963.52	\$569.99	\$2,279.96	\$732.95	\$2,931.80	\$1,825.00	\$7,300.00
	Brand & Model Bidding: _____			Bosch DHR-0800B-050A		Security Labs SLD262		Everfocus ECOR8D/500		IDView CY-5008	
2	16 channel video surveillance Digital Video Recorder system unit	4	ea	\$ 4,680.88	\$ 18,723.52	\$ 719.99	\$ 2,879.96	\$ 1,500.00	\$6,000.00	\$2,277.00	\$9,108.00
	Brand & Model Bidding: _____			Bosch DHR-1600B-050A		Security Labs SLD263		Everfocus EPARA 16 D3/ITB		IDView CY-5016	
Payment Terms				30% Net 30 Days		0 Days					
Delivery Days ARO				30		20		30			
Comments											

											AWARD See Explanation	
Line #	Digital Video Surveillance Recorders			Compulan Center Inc.		Fire Protection Service Corp.		Fire Protection Service Corp		Halifax Security Inc		
	Description	Qty	UOM	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price	
1	8 channel video surveillance Digital Video Recorder system unit	4	ea	\$2,225.00	\$ 8,900.00	3284.21	13136.84	\$4,872.63	\$ 19,490.52	\$4,720.00	\$ 18,880.00	
	Brand & Model Bidding:_____			IDView CY-5008 3TB		Bosch Divar XF # DHR-0800B-050A		Bosch Divar XF # DHR-0800B-300A		Bosch DHR 0800B-300A		
2	16 channel video surveillance Digital Video Recorder system unit	4	ea	\$2,677.00	\$10,708.00	\$3,894.74	\$15,578.96	\$5,630.53	\$22,522.12	\$5,498.00	\$21,992.00	
	Brand & Model Bidding:_____			IDView CY-5016 3TB		Bosch Divar XF # DHR-1600B-050A		Bosch Divar XF # DHR-1600B-300A		Bosch DHR 0800B-300A		
Payment Terms				1% 10 Days						N30 Days		
Delivery Days ARO				30		21		21		7-10 unless back ordered by Bosch		
Comments										If you need to add a Raid license add \$415-per license		

Line #	Digital Video Surveillance Recorders			Ingersoll Rand Security Technologies		International Business Systems		Inter Pacific, Inc		Martin's Security Depot, Inc	
	Description	Qty	UOM	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price
1	8 channel video surveillance Digital Video Recorder system unit	4	ea	\$5,760.00	\$ 23,040.00	\$1,694.94	\$ 6,779.76	\$6,066.25	\$ 24,265.00	\$4,959.00	\$ 19,836.00
	Brand & Model Bidding: _____			Bosch DHR-0800B-300A		ARM Electronics JH8D1000		Bosch Divar XF DHR0800B300A		Bosch Divar XF Int. DVD 8 CH 3TB DHR-0800B-300A	
2	16 channel video surveillance Digital Video Recorder system unit	4	ea	\$6,540.00	\$26,160.00	\$2,118.94	\$8,475.76	\$7,092.50	\$28,370.00	\$5,799.00	\$23,196.00
	Brand & Model Bidding: _____			Bosch DHR-1600B-300A		ARM Electronics JH16D1000		Bosch Divar XF DHR1600B300A		Bosch Divar XF Int. DVD 16 CH 3TB DHR-1600B-300A	
Payment Terms						1% 10 Days		0% 30 Days			
Delivery Days ARO						14		21		7	
Comments											

Line #	Digital Video Surveillance Recorders			M3T Corporation		Peachtree Telecom		Precise Digital		Ready 2 Protect	
	Description	Qty	UOM	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price
1	8 channel video surveillance Digital Video Recorder system unit	4	ea	\$6,163.00	\$ 24,652.00	\$5,100.00	\$ 20,400.00	\$6,884.00	\$ 27,536.00	\$2,896.00	\$ 11,584.00
	Brand & Model Bidding: _____			Bosch DHR-0800A-300A		Bosch DHR00800B300A		InVidia INV1-3000R-8		IC Realtime DVR FLEX-8EM	
2	16 channel video surveillance Digital Video Recorder system unit	4	ea	\$7,206.00	\$28,824.00	\$5,960.00	\$23,840.00	\$8,115.00	\$32,460.00	\$3,098.00	\$12,392.00
	Brand & Model Bidding: _____			Bosch DHR-1600B-300A		Bosch DHR1600B300A		InVidia INV1-3000R-16		IC Realtime DVR FLEX-16EM	
Payment Terms				1% 10 Days				0 Days		1% 10 Days	
Delivery Days ARO				60						30	
Comments											

Line #	Digital Video Surveillance Recorders			Security Cameras Direct		Security Equipment Inc.		Security Group One, Inc.		Urban Contractors	
	Description	Qty	UOM	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price	Unit Price	Extended Price
1	8 channel video surveillance Digital Video Recorder system unit	4	ea	\$4,804.95	\$ 19,219.80	\$4,827.00	\$ 19,308.00	\$4,852.65	\$ 19,410.60	\$7,500.00	\$ 30,000.00
	Brand & Model Bidding:_____			Bosch DHR0800B300A		Bosch Divar XF		Bosch DHR0800B300A		Bosch DHR-800A-150A (1.5 TB)	
2	16 channel video surveillance Digital Video Recorder system unit	4	ea	\$5,617.82	\$22,471.28	\$7,829.00	\$31,316.00	\$5,673.70	\$22,694.80	\$10,000.00	\$40,000.00
	Brand & Model Bidding:_____			Bosch DHR1600B300A		Bosch Divar XF		Bosch DHR1600B300A		Bosch DHR-1600A-300A (3 TB)	
Payment Terms				0 Days				Net 30 Days		Net 30 Days	
Delivery Days ARO				10		30		14		30	
Comments											

No Bid
Samsung/GVI

AWARD EXPLANATION: The following low bidders failed to meet the minimum required specifications in the following areas as referenced below:

1st Apparent Low Bidder - Business Services:

For the Minimum 8 Channel Digital Video Recorder – Business Services failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet minimum specifications of 3.B., 3.C., 3.D., 3.H. and 3.Q. under the “Capabilities” Section.
- Did not meet minimum specifications of 6.F. under the “Recording” section.
- Did not meet the minimum specifications of the minimum hard drive size of 3TB or the equivalent 3,000GB as specified in Addendum 1, Question 2 and in Addendum 3, Question 1.

For the Minimum 16 Channel Digital Video Recorder – Business Services failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet minimum specifications of 3.B., 3.C., 3.D., 3.H. and 3.Q. under the “Capabilities” Section.
- Did not meet minimum specifications of 6.F. under the “Recording” section.

2nd Apparent Low Bidder - Clark Security Products:

For the Minimum 8 Channel Digital Video Recorder – Clark Security Products failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 3.B., 3.C., 3.D., 3.H., under the “Capabilities” section.
- Did not meet the minimum specifications of 4.A. and 4.B. under the “Alarms” Section.
- Did not meet the minimum specifications of 5.F. and 5.H. under the “Alarm Functions” section.
- Did not meet the minimum specifications of 7.B., 7.C., and 7.D. of the “Audio” section.
- Did not meet the minimum specifications of 9.A., 9.B., 9.C., 9.D., and 9.F. of the “Hard Drives” section.
- Did not meet the minimum specifications of 10.B. under the section “Warranty” Section.

For the Minimum 16 Channel Digital Video Recorder – Clark Security Products failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 3.D. and 3.N. under the “Capabilities” Section.
- Did not meet the minimum specifications of 4.A. under the “Alarms” Section.
- Did not meet the minimum specifications of 7.B. and 7.C. of the “Audio” Section.
- Did not meet the minimum specifications of 9.A., 9.B., 9.C., 9.D., 9.E. and 9.F. of the “Hard Drives” section
- Did not meet the minimum specifications of 10.B. of the “Warranty” Section.

3rd Apparent Low Bidder - International Business Systems:

For the Minimum 8 Channel Digital Video Recorder – International Business Systems failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 2.A.1., 2.A.2, and 2.A.3. and 2.E. and 2.F. under the “Operations” section.
- Did not meet the minimum specifications of 3.B., 3.D., 3.E., 3.G., 3.H., 3.J., 3.M., 3.N., 3.Q., and 3.R. under the “Capabilities” section.
- Did not meet the minimum specifications of 4.A. and 4.B. under the “Alarms” section.
- Did not meet the minimum specifications of 6.F. under the “Recording” section.
- Did not meet the minimum specifications of 7.D. of the “Audio” section.
- Did not meet the minimum specifications of 9.A., 9.B., 9.C., 9.D. and 9.F. of the “Hard Drives” section.

For the Minimum 16 Channel Digital Video Recorder – International Business Systems, Inc. failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 2.A.1., 2.A.2, and 2.A.3. and 2.E. and 2.F. under the “Operations” section.
- Did not meet the minimum specifications of 3.B., 3.D., 3.E., 3.G., 3.H., 3.J., 3.M., 3.N., 3.Q., and 3.R. under the “Capabilities” section.
- Did not meet the minimum specifications of 4.A. and 4.B. under the “Alarms” section.
- Did not meet the minimum specifications of 6.F. and 6.G. under the “Recording” section.
- Did not meet the minimum specifications of 7.D. of the “Audio” section.
- Did not meet the minimum specifications of 9.A., 9.B., 9.C., 9.D. and 9.F. of the “Hard Drives” section.

4th Apparent Low Bidder - Compulan Center – Bid 1:

For the Minimum 8 Channel Digital Video Recorder –Compulan Center Bid 1 failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 3.C., 3.D., 3.H. and 3.M. under the “Capabilities” section.
- Did not meet the minimum specifications of 4.A. and 4.B. under the “Alarms” section.
- Did not meet the minimum specifications of the minimum hard drive size of 3TB or the equivalent 3,000GB as specified in Addendum 1, Question 2 and in Addendum 3, Question 1.

For the Minimum 16 Channel Digital Video Recorder – Compulan Center Bid 1 failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 3.C., 3.D., 3.H. and 3.M. under the “Capabilities” section.
- Did not meet the minimum specifications of 4.A. and 4.B. under the “Alarms” section.
- Did not meet the minimum specifications of the minimum hard drive size of 3TB or the equivalent 3,000GB as specified in Addendum 1, Question 2 and in Addendum 3, Question 1.

5th Apparent Low Bidder - Compulan Center – Bid 2:

For the Minimum 8 Channel Digital Video Recorder – Compulan Center Bid 2 failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 3.C., 3.D., and 3.M. under the “Capabilities” section.
- Did not meet the minimum specifications of 4.A. and 4.B. under the “Alarms” section.

For the Minimum 16 Channel Digital Video Recorder – Compulan Center Bid 2 failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 3.C., 3.D., and 3.M. under the “Capabilities” section.
- Did not meet the minimum specifications of 4.A. and 4.B. under the “Alarms” section.

6th Apparent Low Bidder –Ready 2 Protect:

For the Minimum 8 Channel Digital Video Recorder – Ready 2 Protect failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 3.D., 3.E., 3.Q., 3.R. under the “Capabilities” section.
- Did not meet the minimum specifications of 7.C. under the “Audio” section.
- Did not meet the minimum specifications of 9.A. under the “Hard Drives” section.

For the Minimum 16 Channel Digital Video Recorder – Ready 2 Protect failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of 3.D., 3.E., 3.Q., 3.R. under the “Capabilities” section.
- Did not meet the minimum specifications of 7.C. under the “Audio” section.
- Did not meet the minimum specifications of 9.A. under the “Hard Drives” section.

7th Apparent Low Bidder – Fire Protection Services Corp. – Bid 1:

For the Minimum 8 Channel Digital Video Recorder – Fire Protection Services Corp. failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of the minimum hard drive size of 3TB or the equivalent 3,000GB as specified in Addendum 1, Question 2 and in Addendum 3, Question 1.

For the Minimum 16 Channel Digital Video Recorder – Fire Protection Services Corp. failed to meet the minimum required specifications in the following areas as referenced below:

- Did not meet the minimum specifications of the minimum hard drive size of 3TB or the equivalent 3,000GB as specified in Addendum 1, Question 2 and in Addendum 3, Question 1.

8th Apparent Low Bidder – Aprisa Technology:

For the Minimum 8 Channel Digital Video Recorder – Aprisa Technology failed to meet the minimum required specifications in the following areas as referenced below:

- ➔ Did not meet the minimum specifications of 10.B. and 10.C. under the “Warranty” Section.
- ➔ Did not meet the minimum specifications of the minimum hard drive size of 3TB or the equivalent 3,000GB as specified in Addendum 1, Question 2 and in Addendum 3, Question 1.

For the Minimum 16 Channel Digital Video Recorder – Aprisa Technology failed to meet the minimum required specifications in the following areas as referenced below:

- ➔ Did not meet the minimum specifications of 10.B. and 10.C. under the “Warranty” Section.
- ➔ Did not meet the minimum specifications of the minimum hard drive size of 3TB or the equivalent 3,000GB as specified in Addendum 1, Question 2 and in Addendum 3, Question 1.

9th Apparent Low Bidder – Halifax Security (DBA North American Video):

For the Minimum 8 Channel Digital Video Recorder - Meets Specifications

For the Minimum 16 Channel Digital Video Recorder - Meets Specifications