

2021 INSPECTION

Lincoln Correctional Center

3216 West Van Dorn, Lincoln, Nebraska 68522

TOTALREPORT®

INSPECTION AND CONDITION ASSESSMENT REPORTING

Inspection Provider: [REDACTED]

Lead Inspector: [REDACTED]

Assistant Inspector:

Scope: Full

Frequency:

Account Manager: [REDACTED]

Account: Lincoln Correctional Center

Address: 3216 West Van Dorn, Lincoln, Nebraska 68522

Fire Alarm Inspection Summary

Result Totals

Devices	Duct Detector	Pull Station	Relays	Smoke Detector	Tamper	Thermal/Heat Detector	Waterflow sprinkler
Passed	-	-	-	219	-	-	-
Mitigated	-	-	-	-	-	-	-
New - Passed	-	-	-	-	-	-	-
Failed	-	-	-	-	-	-	-
Removed	-	-	-	-	-	-	-
Not Inspected	21	34	6	-	18	61	16
Total	21	34	6	219	18	61	16

Panel Information

Type	200 - FACP
Location	Sprinkler and relay modules Boiler Room
Model	2020
Manufacturer	notifier
Voltage	120VAC

This inspection was performed on 1/6/2021 in accordance with applicable requirements.

1st Floor heats and pulls Fire Alarm Results

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
1	Thermal/Heat Detector		Notifier	FST751	M-5	1/6/2021 7:36 AM	Not Inspected	
2	Pull Station				Boiler Room	1/6/2021 7:36 AM	Not Inspected	
3	Thermal/Heat Detector		Notifier	FST751	Chiller Area	1/6/2021 7:36 AM	Not Inspected	
4	Thermal/Heat Detector		Notifier	FST751	Chiller Office	1/6/2021 7:36 AM	Not Inspected	
5	Pull Station				Chiller Area	1/6/2021 7:36 AM	Not Inspected	
6	Thermal/Heat Detector		Notifier	FST751	Chiller Area	1/6/2021 7:36 AM	Not Inspected	
7	Pull Station				Chiller Exit	1/6/2021 7:36 AM	Not Inspected	
8	Thermal/Heat Detector		Notifier	FST751	Carpentry Shop	1/6/2021 7:36 AM	Not Inspected	
9	Thermal/Heat Detector		Notifier	FST751	Carpentry Shop	1/6/2021 7:36 AM	Not Inspected	
10	Pull Station				Carpentry Shop	1/6/2021 7:36 AM	Not Inspected	
11	Pull Station				Hall 272	1/6/2021 7:36 AM	Not Inspected	
12	Thermal/Heat Detector		Notifier	FST751	M-8	1/6/2021 7:36 AM	Not Inspected	
13	Pull Station				Library	1/6/2021 7:36 AM	Not Inspected	
14	Thermal/Heat Detector		Notifier	FST751	Library L-2	1/6/2021 7:36 AM	Not Inspected	
15	Thermal/Heat Detector		Notifier	FST751	Library Closet	1/6/2021 7:36 AM	Not Inspected	
16	Thermal/Heat Detector		Notifier	FST751	Central Dining Electrical	1/6/2021 7:36 AM	Not Inspected	
17	Pull Station				Central Dining	1/6/2021 7:36 AM	Not Inspected	
18	Pull Station				Central Dining	1/6/2021 7:36 AM	Not Inspected	
19	Thermal/Heat Detector		Notifier	FST751	Central Dining Kitchen	1/6/2021 7:36 AM	Not Inspected	
20	Thermal/Heat Detector		Notifier	FST751	Central Dining Wash Room	1/6/2021 7:36 AM	Not Inspected	
21	Thermal/Heat Detector		Notifier	FST751	Central Dining CD-3	1/6/2021 7:36 AM	Not Inspected	
22	Thermal/Heat Detector		Notifier	FST751	S-3	1/6/2021 7:36 AM	Not Inspected	
23	Pull Station				Canteen	1/6/2021 7:36 AM	Not Inspected	
24	Thermal/Heat Detector		Notifier	FST751	Canteen	1/6/2021 7:36 AM	Not Inspected	
25	Thermal/Heat Detector		Notifier	FST751	Canteen Supplies	1/6/2021 7:36 AM	Not Inspected	
26	Thermal/Heat Detector		Notifier	FST751	Canteen office closet	1/6/2021 7:36 AM	Not Inspected	
27	Pull Station				Turn Key	1/6/2021 7:36 AM	Not Inspected	
28	Thermal/Heat Detector		Notifier	FST751	Gym G-10	1/6/2021 7:36 AM	Not Inspected	
28	Pull Station				Gym Exit	1/6/2021 7:36 AM	Not Inspected	
29	Thermal/Heat Detector		Notifier	FST751	Gym G-11	1/6/2021 7:36 AM	Not Inspected	
30	Thermal/Heat Detector		Notifier	FST751	Gym G-7	1/6/2021 7:36 AM	Not Inspected	
31	Thermal/Heat Detector		Notifier	FST751	Gym locker Room	1/6/2021 7:36 AM	Not Inspected	
32	Pull Station				E-7 Control Room	1/6/2021 7:36 AM	Not Inspected	
33	Pull Station				E-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
34	Thermal/Heat Detector		Notifier	FST751	E-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
35	Duct Detector				E-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
36	Pull Station				E-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
37	Thermal/Heat Detector		Notifier	FST751	E-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
38	Duct Detector				E-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
39	Pull Station				D-7 control	1/6/2021 7:36 AM	Not Inspected	

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
40	Pull Station				D-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
41	Thermal/Heat Detector		Notifier	FST751	D-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
42	Duct Detector				D-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
43	Duct Detector				D-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
44	Thermal/Heat Detector		Notifier	FST751	D-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
45	Pull Station				D-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
46	Pull Station				C control Room	1/6/2021 7:36 AM	Not Inspected	
47	Pull Station				C-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
48	Thermal/Heat Detector		Notifier	FST751	C-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
49	Duct Detector				C-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
50	Duct Detector				C-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
51	Thermal/Heat Detector		Notifier	FST751	C-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
52	Pull Station				C-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
53	Thermal/Heat Detector		Notifier	FST751	Control Unit Mech Room	1/6/2021 7:36 AM	Not Inspected	
54	Pull Station				Control unit Mech Room	1/6/2021 7:36 AM	Not Inspected	
55	Duct Detector				Control Unit Mech Room	1/6/2021 7:36 AM	Not Inspected	
56	Pull Station				Mental Health Mech Room	1/6/2021 7:36 AM	Not Inspected	
57	Duct Detector				Mental Health Mech Room	1/6/2021 7:36 AM	Not Inspected	
58	Thermal/Heat Detector		Notifier	FST751	Mental Health Mech Room	1/6/2021 7:36 AM	Not Inspected	
59	Thermal/Heat Detector		Notifier	FST751	Compound Conference Room	1/6/2021 7:36 AM	Not Inspected	
60	Pull Station				Compound Confrence Room	1/6/2021 7:36 AM	Not Inspected	
61	Pull Station				Lower Mental Health	1/6/2021 7:36 AM	Not Inspected	
62	Thermal/Heat Detector		Notifier	FST751	religious center P-17	1/6/2021 7:36 AM	Not Inspected	
63	Thermal/Heat Detector		Notifier	FST751	religious center P-18	1/6/2021 7:36 AM	Not Inspected	
64	Thermal/Heat Detector		Notifier	FST751	religious center P-19	1/6/2021 7:36 AM	Not Inspected	
65	Pull Station				b control room b-7	1/6/2021 7:36 AM	Not Inspected	
66	Pull Station				B1 Mech room	1/6/2021 7:36 AM	Not Inspected	
67	Thermal/Heat Detector		Notifier	FST751	B-1Mech Room	1/6/2021 7:36 AM	Not Inspected	
68	Duct Detector				B-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
69	Thermal/Heat Detector		Notifier	FST751	B-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
70	Duct Detector				B-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
71	Pull Station				B-2 Mech room	1/6/2021 7:36 AM	Not Inspected	
72	Pull Station				A-Control Room A-7	1/6/2021 7:36 AM	Not Inspected	
73	Pull Station				A-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
74	Duct Detector				A-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
75	Thermal/Heat Detector		Notifier	FST751	A-1 Mech Room	1/6/2021 7:36 AM	Not Inspected	
76	Thermal/Heat Detector		Notifier	FST751	A-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
77	Duct Detector				A-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	
78	Duct Detector				A-2 Mech Room	1/6/2021 7:36 AM	Not Inspected	

2nd Floor heats and pulls Fire Alarm Results

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
1	Pull Station				Front Entrance	1/6/2021 7:36 AM	Not Inspected	
2	Thermal/Heat Detector		Notifier	FST751	Janitor Closet 0-19	1/6/2021 7:36 AM	Not Inspected	
3	Thermal/Heat Detector		Notifier	FST751	Server Closer 0-6	1/6/2021 7:36 AM	Not Inspected	
4	Thermal/Heat Detector		Notifier	FST751	Entrance Search Room	1/6/2021 7:36 AM	Not Inspected	
5	Thermal/Heat Detector		Notifier	FST751	Visiting Room Storage	1/6/2021 7:36 AM	Not Inspected	
6	Pull Station				Control Room	1/6/2021 7:36 AM	Not Inspected	
7	Thermal/Heat Detector		Notifier	FST751	W-1 Storage	1/6/2021 7:36 AM	Not Inspected	
8	Thermal/Heat Detector		Notifier	FST751	W-1 Storage 2	1/6/2021 7:36 AM	Not Inspected	
9	Thermal/Heat Detector		Notifier	FST751	W-1 Storage 3	1/6/2021 7:36 AM	Not Inspected	
10	Thermal/Heat Detector		Notifier	FST751	W-1 Storage 3	1/6/2021 7:36 AM	Not Inspected	
11	Thermal/Heat Detector		Notifier	FST751	CC-5	1/6/2021 7:36 AM	Not Inspected	
12	Pull Station				Elevators	1/6/2021 7:36 AM	Not Inspected	
13	Pull Station				Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
14	Duct Detector				Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
15	Thermal/Heat Detector		Notifier	FST751	Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
16	Thermal/Heat Detector		Notifier	FST751	Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
17	Duct Detector				Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
18	Duct Detector				Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
19	Duct Detector				Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
20	Duct Detector				Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
21	Duct Detector				Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
22	Thermal/Heat Detector		Notifier	FST751	Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
23	Duct Detector				Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
24	Thermal/Heat Detector		Notifier	FST751	Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
25	Duct Detector				Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
26	Thermal/Heat Detector		Notifier	FST751	Upper Mech Room	1/6/2021 7:36 AM	Not Inspected	
27	Thermal/Heat Detector		Notifier	FST751	K-10	1/6/2021 7:36 AM	Not Inspected	
28	Thermal/Heat Detector		Notifier	FST751	K-12	1/6/2021 7:36 AM	Not Inspected	
29	Thermal/Heat Detector		Notifier	FST751	K-14	1/6/2021 7:36 AM	Not Inspected	
30	Thermal/Heat Detector		Notifier	FST751	K-13	1/6/2021 7:36 AM	Not Inspected	
31	Thermal/Heat Detector		Notifier	FST751	CC-8	1/6/2021 7:36 AM	Not Inspected	
32	Thermal/Heat Detector		Notifier	FST751	CC-8	1/6/2021 7:36 AM	Not Inspected	
33	Thermal/Heat Detector		Notifier	FST751	Kitchen Storage	1/6/2021 7:36 AM	Not Inspected	
34	Thermal/Heat Detector		Notifier	FST751	Kitchen	1/6/2021 7:36 AM	Not Inspected	
35	Thermal/Heat Detector		Notifier	FST751	Kitchen	1/6/2021 7:36 AM	Not Inspected	
36	Thermal/Heat Detector		Notifier	FST751	Kitchen	1/6/2021 7:36 AM	Not Inspected	
37	Pull Station				Entrance Search Room	1/6/2021 7:36 AM	Not Inspected	

Loop 1 Smoke Detectors Fire Alarm Results

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
1	Smoke Detector	L1D01	Notifier	FSP-851	Tool Rm	1/6/2021 1:49 PM	Passed	
2	Smoke Detector	L1D02	Notifier	FSP-851	Tool Rm Storage	1/6/2021 1:49 PM	Passed	
3	Smoke Detector	L1D03	Notifier	FSP-851	Tool Rm Check out	1/6/2021 1:49 PM	Passed	
4	Smoke Detector	L1D04	Notifier	FSP-851	Hall by tool rm	1/6/2021 1:49 PM	Passed	
5	Smoke Detector	L1D05	Notifier	FSP-851	Entry Vestibule	1/6/2021 1:49 PM	Passed	
6	Smoke Detector	L1D06	Notifier	FSP-851	Left Restroom	1/6/2021 1:49 PM	Passed	
7	Smoke Detector	L1D08	Notifier	FSP-851	Asst Maint Manager M4	1/6/2021 1:49 PM	Passed	
8	Smoke Detector	L1D10	Notifier	FSP-851	Maint clerk office	1/6/2021 1:48 PM	Passed	
9	Smoke Detector	L1D11	Notifier	FSP-851	Elevator lobby	1/6/2021 1:48 PM	Passed	
10	Smoke Detector	L1D13	Notifier	FSP-851	Storage behind elevator	1/6/2021 1:48 PM	Passed	
11	Smoke Detector	L1D14	Notifier	FSP-851	Legal Library storage	1/6/2021 1:48 PM	Passed	
12	Smoke Detector	L1D15	Notifier	FSP-851	Legal Library	1/6/2021 1:48 PM	Passed	
13	Smoke Detector	L1D16	Notifier	FSP-851	Library	1/6/2021 1:48 PM	Passed	
14	Smoke Detector	L1D17	Notifier	FSP-851	Library	1/6/2021 1:48 PM	Passed	
15	Smoke Detector	L1D18	Notifier	FSP-851	Library	1/6/2021 1:47 PM	Passed	
16	Smoke Detector	L1D19	Notifier	FSP-851	Library Office L5	1/6/2021 1:46 PM	Passed	
17	Smoke Detector	L1D20	Notifier	FSP-851	Library Storage L2	1/6/2021 1:46 PM	Passed	
18	Smoke Detector	L1D22	Notifier	FSP-851	Hall by Library	1/6/2021 1:45 PM	Passed	
19	Smoke Detector	L1D23	Notifier	FSP-851	Hall by School	1/6/2021 1:45 PM	Passed	
20	Smoke Detector	L1D24	Notifier	FSP-851	Hall by Dining rm	1/6/2021 1:44 PM	Passed	
21	Smoke Detector	L1D25	Notifier	FSP-851	Hall by Maj. Off. Area	1/6/2021 1:44 PM	Passed	
22	Smoke Detector	L1D26	Notifier	FSP-851	Hall by Multipurpose	1/6/2021 1:43 PM	Passed	
23	Smoke Detector	L1D27	Notifier	FSP-851	TurnKey Area	1/6/2021 1:43 PM	Passed	
24	Smoke Detector	L1D28	Notifier	FSP-851	Classroom S16	1/6/2021 1:43 PM	Passed	
25	Smoke Detector	L1D29	Notifier	FSP-851	Classroom S13	1/6/2021 1:42 PM	Passed	
26	Smoke Detector	L1D30	Notifier	FSP-851	Classroom S12	1/6/2021 1:42 PM	Passed	
27	Smoke Detector	L1D31	Notifier	FSP-851	Classroom S11	1/6/2021 1:41 PM	Passed	
28	Smoke Detector	L1D32	Notifier	FSP-851	Classroom S10	1/6/2021 1:41 PM	Passed	
29	Smoke Detector	L1D33	Notifier	FSP-851	Hall in School	1/6/2021 1:40 PM	Passed	
30	Smoke Detector	L1D35	Notifier	FSP-851	Staff Restroom S15	1/6/2021 1:40 PM	Passed	
31	Smoke Detector	L1D36	Notifier	FSP-851	Inmate Restroom S17	1/6/2021 1:39 PM	Passed	
32	Smoke Detector	L1D38	Notifier	FSP-851	Cafeteria Ceiling	1/6/2021 1:39 PM	Passed	
33	Smoke Detector	L1D39	Notifier	FSP-851	Cafeteria Ceiling	1/6/2021 1:38 PM	Passed	
34	Smoke Detector	L1D40	Notifier	FSP-851	Cafeteria Ceiling	1/6/2021 1:38 PM	Passed	
35	Smoke Detector	L1D41	Notifier	FSP-851	Southeast Vestibule	1/6/2021 1:37 PM	Passed	
36	Smoke Detector	L1D42	Notifier	FSP-851	Cafeteria Ceiling	1/6/2021 1:37 PM	Passed	
37	Smoke Detector	L1D43	Notifier	FSP-851	Cafeteria Ceiling	1/6/2021 1:36 PM	Passed	
38	Smoke Detector	L1D44	Notifier	FSP-851	Cafeteria Ceiling	1/6/2021 1:36 PM	Passed	
39	Smoke Detector	L1D45	Notifier	FSP-851	Cafeteria Ceiling	1/6/2021 1:35 PM	Passed	
40	Smoke Detector	L1D46	Notifier	FSP-851	Cafeteria Ceiling	1/6/2021 1:35 PM	Passed	

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
41	Smoke Detector	L1D49	Notifier	FSP-851	Storage Room	1/6/2021 1:34 PM	Passed	
42	Smoke Detector	L1D51	Notifier	FSP-851	Restroom	1/6/2021 1:34 PM	Passed	
43	Smoke Detector	L1D52	Notifier	FSP-851	Security Office	1/6/2021 1:33 PM	Passed	
44	Smoke Detector	L1D57	Notifier	FSP-851	Locker Rm Restroom	1/6/2021 1:33 PM	Passed	
45	Smoke Detector	L1D59	Notifier	FSP-851	Gym Office G5	1/6/2021 1:32 PM	Passed	
46	Smoke Detector	L1D60	Notifier	FSP-851	Office S6	1/6/2021 1:32 PM	Passed	
47	Smoke Detector	L1D61	Notifier	FSP-851	Office S7	1/6/2021 1:31 PM	Passed	
48	Smoke Detector	L1D62	Notifier	FSP-851	Center Open Office	1/6/2021 1:31 PM	Passed	
49	Smoke Detector	L1D68	Notifier	FSP-851	Weight Room	1/6/2021 1:30 PM	Passed	
50	Smoke Detector	L1D64	Notifier	FSP-851	Office S4	1/6/2021 1:30 PM	Passed	
51	Smoke Detector	L1D69	Notifier	FSP-851	Weight Room	1/6/2021 1:29 PM	Passed	
52	Smoke Detector	L1D65	Notifier	FSP-851	Restroom Entrance	1/6/2021 1:29 PM	Passed	
53	Smoke Detector	L1D71	Notifier	FSP-851	Hall by Pop Room	1/6/2021 1:28 PM	Passed	
54	Smoke Detector	L1D72	Notifier	FSP-851	Hall by Office	1/6/2021 1:28 PM	Passed	
55	Smoke Detector	L1D74	Notifier	FSP-851	Gym Ceiling	1/6/2021 1:27 PM	Passed	
56	Smoke Detector	L1D75	Notifier	FSP-851	Gym Ceiling	1/6/2021 1:27 PM	Passed	
57	Smoke Detector	L1D76	Notifier	FSP-851	Gym Ceiling	1/6/2021 1:27 PM	Passed	
58	Smoke Detector	L1D77	Notifier	FSP-851	Gym Ceiling	1/6/2021 1:26 PM	Passed	
59	Smoke Detector	L1D78	Notifier	FSP-851	Gym Ceiling	1/6/2021 1:26 PM	Passed	
60	Smoke Detector	L1D79	Notifier	FSP-851	Gym Ceiling	1/6/2021 1:25 PM	Passed	
61	Smoke Detector	L1D80	Notifier	FSP-851	Gym Ceiling	1/6/2021 1:24 PM	Passed	
62	Smoke Detector	L1D81	Notifier	FSP-851	Gym Ceiling	1/6/2021 1:24 PM	Passed	
63	Smoke Detector	L1D82	Notifier	FSP-851	Under Gym Stage (R)	1/6/2021 1:24 PM	Passed	
64	Smoke Detector	L1D83	Notifier	FSP-851	Under Gym Stage (L)	1/6/2021 1:23 PM	Passed	
65	Smoke Detector	L1D84	Notifier	FSP-851	Gym Stage Office G16	1/6/2021 1:23 PM	Passed	
66	Smoke Detector	L1D85	Notifier	FSP-851	Multi Purpose R. R.	1/6/2021 1:22 PM	Passed	
67	Smoke Detector	L1D86	Notifier	FSP-851	Multi Purpose R. R.	1/6/2021 1:22 PM	Passed	
68	Smoke Detector	L1D87	Notifier	FSP-851	Hall by Restroom	1/6/2021 1:21 PM	Passed	
69	Smoke Detector	L1D90	Notifier	FSP-851	East Vestabule	1/6/2021 1:21 PM	Passed	

Loop 3 Smoke Detectors Fire Alarm Results

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
1	Smoke Detector	L3D01	Notifier	FSP-851	Hall by A 1 Door	1/6/2021 2:37 PM	Passed	
2	Smoke Detector	L3D02	Notifier	FSP-851	Hall by A 1 Door	1/6/2021 2:37 PM	Passed	
3	Smoke Detector	L3D03	Notifier	FSP-851	Hall by A 1 Door	1/6/2021 2:37 PM	Passed	
4	Smoke Detector	L3D04	Notifier	FSP-851	Hall by A 1 Door	1/6/2021 2:37 PM	Passed	
5	Smoke Detector	L3D05	Notifier	FSP-851	Hall by A5 Door	1/6/2021 2:36 PM	Passed	
6	Smoke Detector	L3D08	Notifier	FSP-851	Unit A Control Restrm	1/6/2021 2:36 PM	Passed	
7	Smoke Detector	L3D09	Notifier	FSP-851	Unit A Control Rm	1/6/2021 2:36 PM	Passed	
9	Smoke Detector	L3D11	Notifier	FSP-851	Hall by A 2 Door	1/6/2021 2:36 PM	Passed	
10	Smoke Detector	L3D12	Notifier	FSP-851	Hall by A 2 Door	1/6/2021 2:35 PM	Passed	
11	Smoke Detector	L3D13	Notifier	FSP-851	Hall by A 2 Door	1/6/2021 2:35 PM	Passed	
12	Smoke Detector	L3D19	Notifier	FSP-851	Hall by B 1 Door	1/6/2021 2:35 PM	Passed	
13	Smoke Detector	L3D21	Notifier	FSP-851	Hall by B 1 Door	1/6/2021 2:35 PM	Passed	
14	Smoke Detector	L3D22	Notifier	FSP-851	Hall by B 1 Door	1/6/2021 2:34 PM	Passed	
15	Smoke Detector	L3D79	Notifier	FSP-851	Property Storage	1/6/2021 2:20 PM	Passed	
16	Smoke Detector	L3D82	Notifier	FSP-851	Property Storage	1/6/2021 2:20 PM	Passed	
17	Smoke Detector	L3D83	Notifier	FSP-851	Property Storage	1/6/2021 2:19 PM	Passed	
18	Smoke Detector	L3D86	Notifier	FSP-851	Top of Jail Elevator	1/6/2021 2:19 PM	Passed	
19	Smoke Detector	L3D87	Notifier	FSP-851	Jail Elevator equip rm	1/6/2021 2:19 PM	Passed	
20	Smoke Detector	L3D23	Notifier	FSP-851	Hall by B5 door	1/6/2021 2:19 PM	Passed	
21	Smoke Detector	L3D26	Notifier	FSP-851	Unit B control restrm	1/6/2021 2:18 PM	Passed	
22	Smoke Detector	L3D27	Notifier	FSP-851	Unit B control room	1/6/2021 2:18 PM	Passed	
23	Smoke Detector	L3D28	Notifier	FSP-851	Hall by B6 Door	1/6/2021 2:18 PM	Passed	
24	Smoke Detector	L3D29	Notifier	FSP-851	Hall by B2 door	1/6/2021 2:18 PM	Passed	
25	Smoke Detector	L3D30	Notifier	FSP-851	Hall by B2 door	1/6/2021 2:18 PM	Passed	
26	Smoke Detector	L3D31	Notifier	FSP-851	Hall by B2 door	1/6/2021 2:17 PM	Passed	
27	Smoke Detector	L3D37	Notifier	FSP-851	Hall by C1 door	1/6/2021 2:17 PM	Passed	
28	Smoke Detector	L3D38	Notifier	FSP-851	Hall by C1 door	1/6/2021 2:17 PM	Passed	
29	Smoke Detector	L3D39	Notifier	FSP-851	Hall by C1 door	1/6/2021 2:16 PM	Passed	
30	Smoke Detector	L3D40	Notifier	FSP-851	Hall by C1 door	1/6/2021 2:16 PM	Passed	
31	Smoke Detector	L3D41	Notifier	FSP-851	Hall by C6 door	1/6/2021 2:16 PM	Passed	
32	Smoke Detector	L3D44	Notifier	FSP-851	Unit C control restrm	1/6/2021 2:16 PM	Passed	
33	Smoke Detector	L3D45	Notifier	FSP-851	Unit C control room	1/6/2021 2:15 PM	Passed	
34	Smoke Detector	L3D47	Notifier	FSP-851	Hall by C2 door	1/6/2021 2:15 PM	Passed	
35	Smoke Detector	L3D48	Notifier	FSP-851	Hall by C2 door	1/6/2021 2:14 PM	Passed	
36	Smoke Detector	L3D49	Notifier	FSP-851	Hall by C2 door	1/6/2021 2:13 PM	Passed	
37	Smoke Detector	L3D50	Notifier	FSP-851	Hall by C2 door	1/6/2021 2:13 PM	Passed	
38	Smoke Detector	L3D55	Notifier	FSP-851	Hall by Canteen door	1/6/2021 2:13 PM	Passed	
39	Smoke Detector	L3D56	Notifier	FSP-851	Canteen barber shop	1/6/2021 2:13 PM	Passed	
40	Smoke Detector	L3D57	Notifier	FSP-851	Canteen office	1/6/2021 2:12 PM	Passed	
41	Smoke Detector	L3D58	Notifier	FSP-851	Canteen store	1/6/2021 2:12 PM	Passed	

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
42	Smoke Detector	L3D63	Notifier	FSP-851	Conference rm	1/6/2021 2:11 PM	Passed	
43	Smoke Detector	L3D64	Notifier	FSP-851	Conference rm	1/6/2021 2:10 PM	Passed	
44	Smoke Detector	L3D65	Notifier	FSP-851	Conference rm	1/6/2021 2:10 PM	Passed	
45	Smoke Detector	L3D68	Notifier	FSP-851	Hall behind chapel	1/6/2021 2:09 PM	Passed	
46	Smoke Detector	L3D69	Notifier	FSP-851	Hall behind chapel	1/6/2021 2:09 PM	Passed	
47	Smoke Detector	L3D70	Notifier	FSP-851	Hall behind chapel	1/6/2021 2:08 PM	Passed	
48	Smoke Detector	L3D70	Notifier	FSP-851	mental health office	1/6/2021 2:07 PM	Passed	

Loop 2 Smoke Detectors Fire Alarm Results

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
1	Smoke Detector	L2D01	Notifier	FSP-851	Main Entrance	1/6/2021 2:57 PM	Passed	
2	Smoke Detector	L2D02	Notifier	FSP-851	Front Lobby	1/6/2021 2:58 PM	Passed	
3	Smoke Detector	L2D03	Notifier	FSP-851	Front Lobby	1/6/2021 2:58 PM	Passed	
4	Smoke Detector	L2D04	Notifier	FSP-851	Hall by Restroom	1/6/2021 2:58 PM	Passed	
5	Smoke Detector	L2D05	Notifier	FSP-851	Entry Vestibule	1/6/2021 2:58 PM	Passed	
6	Smoke Detector	L2D06	Notifier	FSP-851	Office O4	1/6/2021 2:58 PM	Passed	
7	Smoke Detector	L2D07	Notifier	FSP-851	Office O7	1/6/2021 2:58 PM	Passed	
8	Smoke Detector	L2D08	Notifier	FSP-851	Hall by Room O4	1/6/2021 2:58 PM	Passed	
9	Smoke Detector	L2D09	Notifier	FSP-851	Office O8	1/6/2021 2:59 PM	Passed	
10	Smoke Detector	L2D10	Notifier	FSP-851	Hall by Room O8	1/6/2021 3:09 PM	Passed	
11	Smoke Detector	L2D11	Notifier	FSP-851	Office O9	1/6/2021 3:08 PM	Passed	
12	Smoke Detector	L2D12	Notifier	FSP-851	Office O10	1/6/2021 3:08 PM	Passed	
13	Smoke Detector	L2D13	Notifier	FSP-851	Hall by Room O12	1/6/2021 3:08 PM	Passed	
14	Smoke Detector	L2D14	Notifier	FSP-851	Office O11	1/6/2021 3:08 PM	Passed	
15	Smoke Detector	L2D15	Notifier	FSP-851	Hall by Room O12	1/6/2021 3:07 PM	Passed	
16	Smoke Detector	L2D16	Notifier	FSP-851	Office O12	1/6/2021 3:07 PM	Passed	
17	Smoke Detector	L2D17	Notifier	FSP-851	Hall by Room O13	1/6/2021 3:07 PM	Passed	
18	Smoke Detector	L2D18	Notifier	FSP-851	Wardens Office	1/6/2021 3:06 PM	Passed	
19	Smoke Detector	L2D19	Notifier	FSP-851	Conf. Room O6	1/6/2021 3:06 PM	Passed	
20	Smoke Detector	L2D20	Notifier	FSP-851	Conf. Room O6	1/6/2021 3:06 PM	Passed	
21	Smoke Detector	L2D23	Notifier	FSP-851	Men's Restroom O21	1/6/2021 3:06 PM	Passed	
22	Smoke Detector	L2D24	Notifier	FSP-851	Women's Restroom O21	1/6/2021 3:05 PM	Passed	
23	Smoke Detector	L2D25	Notifier	FSP-851	Mail Room	1/6/2021 2:59 PM	Passed	
24	Smoke Detector	L2D26	Notifier	FSP-851	Copy Room	1/6/2021 2:59 PM	Passed	
25	Smoke Detector	L2D27	Notifier	FSP-851	Office O15	1/6/2021 2:59 PM	Passed	
26	Smoke Detector	L2D28	Notifier	FSP-851	Office O16	1/6/2021 2:59 PM	Passed	
27	Smoke Detector	L2D29	Notifier	FSP-851	Office O17	1/6/2021 2:58 PM	Passed	
28	Smoke Detector	L2D30	Notifier	FSP-851	Control Station R.R.	1/6/2021 2:58 PM	Passed	
29	Smoke Detector	L2D32	Notifier	FSP-851	Entrance Sallyport	1/6/2021 2:58 PM	Passed	
30	Smoke Detector	L2D33	Notifier	FSP-851	Right Restroom	1/6/2021 2:58 PM	Passed	
31	Smoke Detector	L2D34	Notifier	FSP-851	Visitor Entry	1/6/2021 2:58 PM	Passed	
32	Smoke Detector	L2D35	Notifier	FSP-851	Center Restroom	1/6/2021 2:57 PM	Passed	
33	Smoke Detector	L2D36	Notifier	FSP-851	Left Restroom	1/6/2021 2:57 PM	Passed	
34	Smoke Detector	L2D37	Notifier	FSP-851	Visitors Room A	1/6/2021 2:57 PM	Passed	
35	Smoke Detector	L2D38	Notifier	FSP-851	Visitors Room B	1/6/2021 2:57 PM	Passed	
36	Smoke Detector	L2D39	Notifier	FSP-851	Visitors Room C	1/6/2021 2:57 PM	Passed	
38	Smoke Detector	L2D40	Notifier	FSP-851	Visitors Room D	1/6/2021 2:54 PM	Passed	
39	Smoke Detector	L2D41	Notifier	FSP-851	Stairs	1/6/2021 2:54 PM	Passed	
40	Smoke Detector	L2D43	Notifier	FSP-851	Stairs Lobby	1/6/2021 2:54 PM	Passed	
41	Smoke Detector	L2D44	Notifier	FSP-851	Top of Stairs	1/6/2021 2:54 PM	Passed	

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
42	Smoke Detector	L2D45	Notifier	FSP-851	Visitors Ceiling	1/6/2021 2:53 PM	Passed	
43	Smoke Detector	L2D46	Notifier	FSP-851	Visitors Ceiling	1/6/2021 2:53 PM	Passed	
44	Smoke Detector	L2D47	Notifier	FSP-851	Visitors Ceiling	1/6/2021 2:53 PM	Passed	
45	Smoke Detector	L2D48	Notifier	FSP-851	Visitors Ceiling	1/6/2021 2:52 PM	Passed	
46	Smoke Detector	L2D49	Notifier	FSP-851	Parol Hearing Rm	1/6/2021 2:52 PM	Passed	
47	Smoke Detector	L2D50	Notifier	FSP-851	Property Office	1/6/2021 2:52 PM	Passed	
48	Smoke Detector	L2D53	Notifier	FSP-851	Property Restroom	1/6/2021 2:51 PM	Passed	
49	Smoke Detector	L2D56	Notifier	FSP-851	Restroom	1/6/2021 2:51 PM	Passed	
50	Smoke Detector	L2D57	Notifier	FSP-851	Time Keeper Office	1/6/2021 2:50 PM	Passed	
51	Smoke Detector	L2D58	Notifier	FSP-851	Deputy Warden Office	1/6/2021 2:50 PM	Passed	
52	Smoke Detector	L2D59	Notifier	FSP-851	Security Office	1/6/2021 2:50 PM	Passed	
53	Smoke Detector	L2D60	Notifier	FSP-851	Captains Office	1/6/2021 2:50 PM	Passed	
54	Smoke Detector	L2D61	Notifier	FSP-851	Hall by Property	1/6/2021 2:49 PM	Passed	
55	Smoke Detector	L2D62	Notifier	FSP-851	Hall by vending	1/6/2021 2:49 PM	Passed	
56	Smoke Detector	L2D63	Notifier	FSP-851	Top of elev. right	1/6/2021 2:49 PM	Passed	
57	Smoke Detector	L2D64	Notifier	FSP-851	Top of elev. left	1/6/2021 2:41 PM	Passed	
58	Smoke Detector	L2D65	Notifier	FSP-851	Elevator Lobby	1/6/2021 2:41 PM	Passed	
59	Smoke Detector	L2D66	Notifier	FSP-851	Top of Basement Stairs	1/6/2021 2:41 PM	Passed	
60	Smoke Detector	L2D68	Notifier	FSP-851	Restroom	1/6/2021 2:41 PM	Passed	
61	Smoke Detector	L2D70	Notifier	FSP-851	Storage Rm K10	1/6/2021 2:40 PM	Passed	
62	Smoke Detector	L2D71	Notifier	FSP-851	Kitchen Office	1/6/2021 2:40 PM	Passed	
63	Smoke Detector	L2D82	Notifier	FSP-851	Hall by bread room	1/6/2021 2:40 PM	Passed	
64	Smoke Detector	L2D89	Notifier	FSP-851	Storage Rm	1/6/2021 2:40 PM	Passed	
65	Smoke Detector	L2D90	Notifier	FSP-851	Upper File Rm	1/6/2021 2:39 PM	Passed	

Loop 4 Smoke Detectors Fire Alarm Results

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
1	Smoke Detector	L4D59	Notifier	FSP-851	Hall By D2 Door	1/6/2021 1:55 PM	Passed	
2	Smoke Detector	L4D61	Notifier	FSP-851	Hall By D2 Door	1/6/2021 1:55 PM	Passed	
3	Smoke Detector	L4D62	Notifier	FSP-851	Hall By D2 Door	1/6/2021 1:55 PM	Passed	
4	Smoke Detector	L4D63	Notifier	FSP-851	Hall By D5 Door	1/6/2021 1:54 PM	Passed	
5	Smoke Detector	L4D66	Notifier	FSP-851	Unit D Control RSTRM	1/6/2021 1:54 PM	Passed	
6	Smoke Detector	L4D67	Notifier	FSP-851	Unit D Control Room	1/6/2021 1:54 PM	Passed	
7	Smoke Detector	L4D68	Notifier	FSP-851	Hall By D6 Door	1/6/2021 1:54 PM	Passed	
8	Smoke Detector	L4D69	Notifier	FSP-851	Hall By D1 Door	1/6/2021 1:54 PM	Passed	
9	Smoke Detector	L4D70	Notifier	FSP-851	Hall By D1 Door	1/6/2021 1:54 PM	Passed	
10	Smoke Detector	L4D71	Notifier	FSP-851	Hall By D1 Door	1/6/2021 1:54 PM	Passed	
11	Smoke Detector	L4D77	Notifier	FSP-851	Elevator lobby jail	1/6/2021 1:53 PM	Passed	
12	Smoke Detector	L4D79	Notifier	FSP-851	Elevator lobby Dental	1/6/2021 1:53 PM	Passed	
13	Smoke Detector	L4D80	Notifier	FSP-851	Medical Dental Hall	1/6/2021 1:53 PM	Passed	
14	Smoke Detector	L4D81	Notifier	FSP-851	Medical Dental Hall	1/6/2021 1:53 PM	Passed	
15	Smoke Detector	L4D08	Notifier	FSP-851	New Chiller Room	1/6/2021 1:53 PM	Passed	
16	Smoke Detector	L4D09	Notifier	FSP-851	New Chiller Room	1/6/2021 1:53 PM	Passed	
17	Smoke Detector	L4D12	Notifier	FSP-851	Corr. by door	1/6/2021 1:52 PM	Passed	
18	Smoke Detector	L4D13	Notifier	FSP-851	1st Detector From LCC	1/6/2021 1:52 PM	Passed	
19	Smoke Detector	L4D14	Notifier	FSP-851	2nd Detector From LCC	1/6/2021 1:52 PM	Passed	
20	Smoke Detector	L4D15	Notifier	FSP-851	3rd Detector From LCC	1/6/2021 1:52 PM	Passed	
21	Smoke Detector	L4D16	Notifier	FSP-851	4th Detector From LCC	1/6/2021 1:52 PM	Passed	
22	Smoke Detector	L4D17	Notifier	FSP-851	5th Detector From LCC	1/6/2021 1:52 PM	Passed	
23	Smoke Detector	L4D18	Notifier	FSP-851	6th Detector From LCC	1/6/2021 1:51 PM	Passed	
24	Smoke Detector	L4D19	Notifier	FSP-851	7th Detector From LCC	1/6/2021 1:51 PM	Passed	
25	Smoke Detector	L4D25	Notifier	FSP-851	Above elevator equipment	1/6/2021 1:51 PM	Passed	
26	Smoke Detector	L4D41	Notifier	FSP-851	Hall by E2 Door	1/6/2021 1:51 PM	Passed	
27	Smoke Detector	L4D42	Notifier	FSP-851	Hall by E2 Door	1/6/2021 1:51 PM	Passed	
28	Smoke Detector	L4D43	Notifier	FSP-851	Hall by E2 Door	1/6/2021 1:51 PM	Passed	
29	Smoke Detector	L4D44	Notifier	FSP-851	Hall by E2 Door	1/6/2021 1:50 PM	Passed	
30	Smoke Detector	L4D45	Notifier	FSP-851	Hall by E6 Door	1/6/2021 1:50 PM	Passed	
31	Smoke Detector	L4D48	Notifier	FSP-851	E control Restroom	1/6/2021 1:50 PM	Passed	
32	Smoke Detector	L4D49	Notifier	FSP-851	E control Room	1/6/2021 1:50 PM	Passed	
33	Smoke Detector	L4D50	Notifier	FSP-851	Hall by E5 Door	1/6/2021 1:50 PM	Passed	
34	Smoke Detector	L4D51	Notifier	FSP-851	Hall by E1 Door	1/6/2021 1:50 PM	Passed	
35	Smoke Detector	L4D52	Notifier	FSP-851	Hall by E1 Door	1/6/2021 1:50 PM	Passed	
36	Smoke Detector	L4D53	Notifier	FSP-851	Hall by E1 Door	1/6/2021 1:50 PM	Passed	
37	Smoke Detector	L4D01	Notifier	FSP-851	telephone equip rm	1/6/2021 1:50 PM	Passed	
38	Smoke Detector	L4D02	Notifier	FSP-851	Boiler rm office	1/6/2021 1:49 PM	Passed	
39	Smoke Detector	L4D03	Notifier	FSP-851	8th Det. from lcc	1/6/2021 1:49 PM	Passed	

Sprinkler and relay modules Fire Alarm Results

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
1	Tamper	L4M64			Sprinkler mnter spklr valve E 1		Not Inspected	
2	Waterflow sprinkler	L4M65			spklr water flow D 2		Not Inspected	
3	Tamper	L4M66			Sprinkler mnter spklr valve D 2		Not Inspected	
4	Waterflow sprinkler	L4M67			spklr water flow D 1		Not Inspected	
5	Tamper	L4M68			Sprinkler mnter spklr valve D 1		Not Inspected	
6	Waterflow sprinkler	L4M69			spklr water flow jail		Not Inspected	
7	Tamper	L4M70			Sprinkler mnter spklr valve jail		Not Inspected	
8	Tamper	L1M10			Sprinkler mnter valve multi purpose		Not Inspected	
9	Tamper	L1M11			Sprinkler multi purpose		Not Inspected	
10	Waterflow sprinkler	L2M03			split water flow office		Not Inspected	
11	Waterflow sprinkler	L2M004			split water flow office area		Not Inspected	
12	Tamper	L3M20			Sprinkler mntr jail elev. valve		Not Inspected	
13	Relays	L3M21			jail elev. capture		Not Inspected	
14	Relays	L3M22			jail elev. alt. Capt.		Not Inspected	
15	Relays	L3M23			jail elev. shunt		Not Inspected	
16	Waterflow sprinkler	L3M51			spklr water flow A 1		Not Inspected	
17	Tamper	L3M52			Sprinkler mntr valve A 1		Not Inspected	
18	Waterflow sprinkler	L3M53			spklr water flow A 2		Not Inspected	
19	Tamper	L3M54			Sprinkler mntr valve A 2		Not Inspected	
20	Tamper	L3M56			Sprinkler mntr valve B 1		Not Inspected	
21	Waterflow sprinkler	L3M55			spklr water flow B 1		Not Inspected	
22	Waterflow sprinkler	L3M57			spklr water flow B 2		Not Inspected	
23	Tamper	L3M58			Sprinkler mntr valve B 2		Not Inspected	
24	Waterflow sprinkler	L3M59			spklr water flow C 1		Not Inspected	
25	Tamper	L3M60			Sprinkler mntr valve C 1		Not Inspected	
26	Waterflow sprinkler	L3M61			spklr flow canteen		Not Inspected	
27	Tamper	L3M62			Sprinkler mntr valve canteen		Not Inspected	
28	Waterflow sprinkler	L3M63			spklr water flow C 2		Not Inspected	
29	Tamper	L3M64			Sprinkler mntr valve C 2		Not Inspected	
30	Waterflow sprinkler	L4M06			spklr water flow main		Not Inspected	
31	Tamper	L4M09			Sprinkler mntr valve tunnel		Not Inspected	
32	Tamper	L4M28			Sprvry mntr tunnel valve		Not Inspected	
33	Relays	L4M31			elevator capture		Not Inspected	
34	Relays	L4M32			elevator alt. capture		Not Inspected	
35	Relays	L4M33			elevator shunt		Not Inspected	
36	Tamper	L4M36			Sprinkler mntr main elev.		Not Inspected	
37	Waterflow sprinkler	L4M36			main elev. waterflow		Not Inspected	
38	Waterflow sprinkler	L4M61			spklr water flow E 2		Not Inspected	
39	Tamper	L4M62			Sprinkler mntr valve E 2		Not Inspected	
40	Waterflow sprinkler	L4M63			spklr water flow E 1		Not Inspected	

Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
200	FACP		notifier	2020	Boller Room	1/6/2021 2:14 PM	Passed	

Battery Results

Panel Number	Type	Parent Location	Position	Voltage	Result	Comments	Date
200	12V 26AH	Sprinkler and relay modules	Boiler Room	13.6	Passed		1/6/2021 2:14 PM
200	12V 26AH	Sprinkler and relay modules	Boiler Room	13.43	Passed		1/6/2021 2:14 PM

Panel Results

Number	Type	Model	Manufacturer	Location	Layout	Result	Comments	Date
200	FACP	2020	notifier	Boiler Room	Sprinkler and relay modules	Passed		1/6/2021 2:14 PM



NFPA72 2016 Testing and Inspection Form

Property: Lincoln Correctional Center

Inspection Date: 1/6/2021

Property Address: 3216 West Van Dorn

Lincoln, Nebraska 68522

1. PROPERTY INFORMATION

Account Name or Property Name	Lincoln Correctional Center
Shipping Street	3216 West Van Dorn
Shipping City	Lincoln
Shipping State/Province	Nebraska
Shipping Zip/Postal Code	68522
Account Phone	
Main Account Email	
Authority Having Jurisdiction	
AHJ Phone Number	
Description of property	
Scope of this instance of inspection	Full

2. TESTING AND MONITORING INFORMATION

Testing Organization

Address

Phone

Monitoring Organization

Address

Monitoring Org Phone

Monitoring Org Email

Monitoring Acct Number

Phone Line one or IP

Phone Line two or IP

Means Of Transmission

3. DOCUMENTATION

Onsite location of the required record documents and site specific software

Is the location of documents and software indicated on the Component list and or layouts?

No

If the location is not indicated as YES above give description of location here

4. DESCRIPTION OF SYSTEM OR SERVICE

4.1 Control unit Make and Model

4.2 Software firmware revision

4.3 System Power

The description Of Primary Power is included in the List of devices on Panels as well as the Disconnecting means location.

4.3.2 Secondary Power

The description of secondary power is included in the listing of devices and capacity is also included

5. AND 7. NOTIFICATIONS MADE BEFORE AND AFTER TESTING**NOTIFICATION MADE PRIOR AND AFTER TESTING**

Description	Time in Testing	Time off testing
Monitoring Org	8:00	1:30
BLDG management		
BLDG occupants		
AHJ		
Other If applicable		

6. TESTING RESULTS

6.1 Control Unit and Related Equipment

6.1 CONTROL UNIT AND RELATED EQUIPMENT

Description	Visual Inspection	Functional test	Comments
Control unit	✓	✓	
Lamps/LEDs/LCDs	✓	✓	
Fuses	✓	✓	
Trouble signals	✓	✓	
Disconnect switches	✓	✓	
Ground-fault monitoring	✓	✓	
Supervision	✓	✓	
Local annunciator	✓	✓	
Remote annunciators			

Remote power panels ✓ ✓

6.2 SECONDARY POWER**6.2 Secondary Power**

Description	Visual Inspection	Functional test	Comments
Battery Condition	✓	✓	
Load voltage	✓	✓	
Discharge test	✓	✓	
Charger test	✓	✓	
Remote panel batteries	✓	✓	

6.3 Alarm And Supervisory Alarm Initiating Device

Attach supplementary device test sheets for all initiating devices.

6.4 Notification Appliances

Attach supplementary appliance test sheets for all notification appliances.

6.5 Interface Equipment

Attach supplementary interface component test sheets for all interface components. Circuit Interface / Signaling Line Circuit Interface / Fire Alarm Control Interface

6.6 SUPERVISING STATION MONITORING**6.6 Supervising Station Monitoring**

Description	Yes	No	Time	Comments
Alarm signal	✓			
Alarm restoration	✓			
Trouble signal	✓			
Trouble restoration	✓			
Supervisory signal	✓			
Supervisory restoration	✓			

6.7 PUBLIC EMERGENCY ALARM REPORTING SYSTEM**6.7 Public Emergency Alarm Reporting System**

Description	Yes	No	Time	Comments
Alarm signal				NA
Alarm restoration				NA
Trouble signal				NA
Trouble restoration				NA
Supervisory signal				NA
Supervisory restoration				NA

8. SYSTEM RESTORED TO NORMAL OPERATION**8. SYSTEM RESTORED TO NORMAL OPERATION**

Date and time Restored to Normal operation.

1-6-2021

9. CERTIFICATION

This system as specified herein has been inspected and tested according to NFPA 72, 2016 edition, Chapter 14.

Inspector Name

Date/Time

Inspector Qualifications

Phone

Company Name

10. DEFECTS OR MALFUNCTIONS NOT CORRECTED ARE LISTED ON THE DEFICIENCIES PAGE OF THIS REPORT**10.1 ACCEPTANCE BY OWNER OR OWNER'S REPRESENTATIVE:**

The listed name below accepted the test report as specified herein:

Property Rep Auto Field

If the Auto Field is not correct who is the responsible party who is accepting the Test report?

Title:

Phone:

Date:

1-6-2021


Panel Results

Number	Type	Model	Manufacturer	Location	Layout	Result	Comments	Date
200	FACP	NFS-320	Notifer	Print Storage Room	1st Floor	Passed		1/6/2021 12:55 PM
201	Power Supply		Notifer	Print Storage Room	1st Floor	Passed		1/6/2021 12:55 PM

2021 INSPECTION

Nebraska Department of Corrections - Lincoln-Jail & CSI

3216 Van Dorn, Lincoln, Nebraska 68522



Inspection Provider:

Lead Inspector:

Account: Nebraska Department of Corrections - Lincoln-Jail & CSI

Assistant Inspector:

Address: 3216 Van Dorn, Lincoln, Nebraska 68522

Scope: Partial

Frequency: 1st Semi-Annual

Account Manager: (800) 274-0888

Fire Alarm 1st Semi-Annual Inspection Summary

Result Totals

Devices	Duct Detector	Power Supply	Pull Station	Smoke Detector
Passed	-	1	-	1
Mitigated	-	-	-	-
New - Passed	-	-	-	-
Failed	-	-	-	-
Removed	-	-	-	-
Not Inspected	5	-	5	-
Total	5	1	5	1

Panel Information

Type	200 - FACP
Location	1st Floor Print Storage Room
Model	NFS-320
Manufacturer	Notifer
Voltage	120

This inspection was performed on 1/6/2021 in accordance with applicable requirements.

1st Floor Fire Alarm Results


Number	Type	Zone/Address	Manufacturer	Model	Location	Date	Result	Comments
1	Pull Station				Print Office	1/6/2021 12:52 PM	Not Inspected	
2	Pull Station				Print Office	1/6/2021 12:52 PM	Not Inspected	
3	Pull Station				Print Office	1/6/2021 12:52 PM	Not Inspected	
4	Pull Station				Print Office	1/6/2021 12:52 PM	Not Inspected	
5	Pull Station				Print Office	1/6/2021 12:52 PM	Not Inspected	
6	Duct Detector				Print Storage Room	1/6/2021 12:52 PM	Not Inspected	
7	Duct Detector				Print Storage Room	1/6/2021 12:52 PM	Not Inspected	
8	Duct Detector				Print Storage Room	1/6/2021 12:52 PM	Not Inspected	
9	Duct Detector				Print Storage Room	1/6/2021 12:52 PM	Not Inspected	
10	Duct Detector				Print Storage Room	1/6/2021 12:52 PM	Not Inspected	
11	Smoke Detector	L1D01	Notifier	FSP851	Above FACP	1/6/2021 12:54 PM	Passed	
200	FACP		Notifier	NFS-320	Print Storage Room	1/6/2021 12:55 PM	Passed	
201	Power Supply		Notifier		Print Storage Room	1/6/2021 12:55 PM	Passed	

Battery Results

Panel Number	Type	Parent Location	Position	Voltage	Result	Comments	Date
200	12V 55AH	1st Floor Print Storage Room		13.7	Passed		1/6/2021 12:52 PM
200	12V 55AH	1st Floor Print Storage Room		13.5	Passed		1/6/2021 12:52 PM
201	12V 8AH	1st Floor Print Storage Room		13.5	Passed		1/6/2021 12:52 PM
201	12V 8AH	1st Floor Print Storage Room		13.8	Passed		1/6/2021 12:52 PM

Panel Results

Number	Type	Model	Manufacturer	Location	Layout	Result	Comments	Date
200	FACP	NFS-320	Notifer	Print Storage Room	1st Floor	Passed		1/6/2021 12:55 PM
201	Power Supply		Notifer	Print Storage Room	1st Floor	Passed		1/6/2021 12:55 PM



NFPA72 2016 Testing and Inspection Form

Property: Nebraska Department of
Corrections - Lincoln-Jail & CSI

Inspection Date: 1/6/2021

Property Address: 3216 Van Dorn
Lincoln, Nebraska 68522

1. PROPERTY INFORMATION

Account Name or Property Name	Nebraska Department of Corrections - Lincoln-Jail & CSI
Shipping Street	3216 Van Dorn
Shipping City	Lincoln
Shipping State/Province	Nebraska
Shipping Zip/Postal Code	68522
Account Phone	(402) 479-5747
Main Account Email	
Authority Having Jurisdiction	
AHJ Phone Number	
Description of property	
Scope of this instance of inspection	Partial

2. TESTING AND MONITORING INFORMATION

Testing Organization	
Address	
Phone	
Monitoring Organization	
Address	
Monitoring Org Phone	
Monitoring Org Email	
Monitoring Acct Number	

Phone Line one or IP

Phone Line two or IP

Means Of Transmission

3. DOCUMENTATION

Onsite location of the required record documents and site specific software

Is the location of documents and software indicated on the Component list and or layouts?

No

If the location is not indicated as YES above give description of location here

4. DESCRIPTION OF SYSTEM OR SERVICE

4.1 Control unit Make and Model

4.2 Software firmware revision

4.3 System Power

The description Of Primary Power is included in the List of devices on Panels as well as the Disconnecting means location.

4.3.2 Secondary Power

The description of secondary power is included in the listing of devices and capacity is also included

5. AND 7. NOTIFICATIONS MADE BEFORE AND AFTER TESTING**NOTIFICATION MADE PRIOR AND AFTER TESTING**

Description	Time in Testing	Time off testing
Monitoring Org	11:30pm	1:30pm
BLDG management	11:30am	1:30pm
BLDG occupants	11:30am	1:30pm
AHJ		
Other If applicable		

6. TESTING RESULTS

6.1 Control Unit and Related Equipment

6.1 CONTROL UNIT AND RELATED EQUIPMENT

Description	Visual Inspection	Functional test	Comments
Control unit	✓	✓	
Lamps/LEDs/LCDs	✓	✓	
Fuses	✓		
Trouble signals	✓	✓	
Disconnect switches	✓	✓	
Ground-fault monitoring	✓	✓	
Supervision	✓	✓	
Local annunciator	✓	✓	

Remote annunciators	✓	✓
Remote power panels	✓	✓

6.2 SECONDARY POWER

6.2 Secondary Power

Description	Visual Inspection	Functional test	Comments
Battery Condition	✓	✓	
Load voltage	✓	✓	
Discharge test	✓	✓	
Charger test	✓	✓	
Remote panel batteries	✓	✓	

6.3 Alarm And Supervisory Alarm Initiating Device

Attach supplementary device test sheets for all initiating devices.

6.4 Notification Appliances

Attach supplementary appliance test sheets for all notification appliances.

6.5 Interface Equipment

Attach supplementary interface component test sheets for all interface components. Circuit Interface / Signaling Line Circuit Interface / Fire Alarm Control Interface

6.6 SUPERVISING STATION MONITORING

6.6 Supervising Station Monitoring

Description	Yes	No	Time	Comments
Alarm signal	✓			
Alarm restoration	✓			
Trouble signal	✓			
Trouble restoration	✓			
Supervisory signal	✓			
Supervisory restoration	✓			

6.7 PUBLIC EMERGENCY ALARM REPORTING SYSTEM

6.7 Public Emergency Alarm Reporting System

Description	Yes	No	Time	Comments
Alarm signal		✓		NA
Alarm restoration		✓		NA
Trouble signal				NA
Trouble restoration		✓		NA
Supervisory signal		✓		NA
Supervisory restoration		✓		NA

8. SYSTEM RESTORED TO NORMAL OPERATION**8. SYSTEM RESTORED TO NORMAL OPERATION**

Date and time Restored to Normal operation.

1/6/2021 1:30pm

9. CERTIFICATION

This system as specified herein has been inspected and tested according to NFPA 72, 2016 edition, Chapter 14.

Inspector Name

Date/Time

Inspector Qualifications

Phone

Company Name

10. DEFECTS OR MALFUNCTIONS NOT CORRECTED ARE LISTED ON THE DEFICIENCIES PAGE OF THIS REPORT**10.1 ACCEPTANCE BY OWNER OR OWNER'S REPRESENTATIVE:**

The listed name below accepted the test report as specified herein:

Property Rep Auto Field

If the Auto Field is not correct who is the responsible party who is accepting the Test report?

Title:

Phone:

Date:

1/6/2021